


PARKER

MAGNETIC PARTICLE INSPECTION INSTRUMENTS



DA400 - Contour Probe. Most popular A.C./D.C. Yoke. Available in various Kit forms. Y400 Yoke Light additional.



B300 - A.C. Contour Probe. Available with Y300 Yoke Light. Also available with GFI Plug.



A210 - Heavy Duty A.C. Contour Probe. Strongest A.C. Field Yoke available. Model DA200 available for A.C./D.C. Operation.



UW115 & UW12 Underwater A.C. and D.C. Yokes.



PL8 & PL10 - Magnetizing Coils. 8" & 10" I.D. Complete with Carrying Case.



BAC310 - Portable, Stand alone Battery Inverted 115VAC Power Supply. Operate A.C. Yokes or other Instruments where normal power sources are unavailable.



DA750 & DA1500 - Portable Mag units. Heavy duty 750 or 1500 AMP. Available with all accessories.



B100 - Our most economical A.C. Contour Probe. Available in 115VAC and 230VAC. May be ordered with the Y400 Yoke Light at extra cost.



DA-400 Shown With "A" Kit items. Kit items are available with dry powder and Wet Fluorescent inspection mediums. Including Black Light and Steel Carrying Case.



WEB SITE: <http://www.parkerNDT.com> 1-800-525-3935

PARKER RESEARCH CORP.

P.O. BOX 1406, DUNEDIN, FLORIDA 34697 USA

Phone: (727) 796-4066, Fax: (727) 797-3941, E-MAIL: sales@parkerNDT.com

MAGNETIC PARTICLE INSPECTION ACCESSORIES



MA7000 - Prod Sets, Prod Replacements, Cables
For all Portable Mag Machines




MG01/MG02 - Magnetic Field Strips
Type 1 (G) and Type 2 (A)



KS100A - Ketos Ring - AS5282
Certified



NA16 - Notch Defect Test Bar.
For Compliance with MIL-STD-271
and NAVSEA-TB-T9074...



MG25 - Magnetometers
(20-0-20), (10-0-10) and
others. W/Certs



PM50 - Permanent Magnet Set.
Available with Optional Kit.



MG50 - Magnetic Pie Gauge W/Certs



Y300/Y400 - Parker Induction Yoke Lights.
Fits Parker B100, B300 and DA400 Contour Probes.



TB10 - Magnetic Weight Lift Test Bars. W/Certs
Available in Single, 3, 4 or 5 Bar Sets.
TB10-SP - 10-Lb Bar with artificial defects



PB5 - Magnetic Powder Blower
Self contained with internal Five Pound
Powder Reservoir and Compressor.
Apply powder evenly to all surfaces.



PB1 - Magnetic Powder
Blower Apply Mag Powder in
any direction.



5170 & 5180 Gauss/Tesla Meters